

information bulletin

April 2020

Howard Road, Dingley Village – Advisory of Proposed Parking Changes

Background

Council is responding to community concerns regarding poor vehicle sightline entering Howard Road from Bridgewater Drive in Dingley Village.

Council Action

Council has conducted a review of driver ability to see oncoming traffic turning right from Bridgewater Drive onto Howard Road. The review determined that sightline exiting right from Bridgewater Drive onto Howard Road to be acceptable. However, sightline at this intersection could be improved by extending the 'no stopping' section on Howard Road to remove the parking space in front of No.122 Howard Road.

An independent review of this intersection also recommended removing this parking space to improve vehicle sightline.

As such, Council will be relocating the existing 'no stopping' sign outside No.122 Howard Road to No.124 Howard Road (please see diagram overleaf).

The 'no stopping' sign will be relocated in the next 2-4 weeks.

Further Information

For further information please contact Traffic Engineer Linda Tran on 1300 653 356

Howard Road, Dingley Village – Advisory of Proposed Parking Changes



